





Verbinden
mit Profil

Zeta P2 problem diagnosis





1. Changing the carbon brushes




Make sure the cable doesn't lie on the sharp edge
Carbon brushes should move easily in the bracket

2. Electronic controller



3. Push VMD button to check function



4. Check the position of the depth adjuster